

FIG. 3




FIG. 4




FIG. 5A




FIG. 5B

0925567 081004
100T80 7952660

Case in which almost no
motion vector is present




FIG. 6A

Case in which motion vectors
in the same direction/size are
distributed over the entire frame




FIG. 6B

Case in which a motion vector
partially located in frame




FIG. 6C

Case in which motion vectors
are distributed in a radiation
manner in frame




FIG. 6D

Case in which there exists a
larger number of motion vectors
in a frame, and directions are not
uniform




FIG. 6E

09925567.081001
T03T80 2952660




FIG. 7

Macro-block in which a mosquito noise is likely to occur

Amount of coded bits concerning I picture




FIG. 9

Amount of coded bits concerning P picture




FIG. 10

0925567.081004

FIG. 8A

FIG. 8B

F I G. 8C

FIG. 12




FIG. 11A




FIG. 11B